


CVUSD Facilities Master Plan




Newbury Park High I Site Analysis

456 N Reino Road I Newbury Park, CA 91320 Conejo Valley Unified School District April 5, 2017



NAC Architecture 837 North Spring Street, 3rd Floor Los Angeles, CA 90012 Contact: 323.475.8075 E-mail: lochoa@nacarchitecture.com Website: www.nacarchitecture.com









Newbury Park High I Site Analysis

456 N Reino Road, Newbury Park, CA 91320 Conejo Valley Unified School District April 5, 2017

Campus Findings

Image A

- Effective traffic circulation and adequate parking stall quantity
- Site layout creates zones for general education, specialty, and athletics
- Central quad with collegiate feel offers space for educational and social gathering

Image B


- Two-story 'finger' buildings create smaller courtyards off the central quad
- Specialty spaces such as the gymnasium, performing arts center and football field/track provide excellent facilities for athletics and arts
- Aging original buildings in need of exterior finish repairs and repaint
- Multiple aging portables housing disparate programs that are isolated from the main educational core of the campus
- Typical Accessibility Challenge

















Newbury Park High I Site Analysis

456 N Reino Road, Newbury Park, CA 91320 Conejo Valley Unified School District April 5, 2017

Campus Findings





campus layout.

Newbury Park High I Site Analysis

456 N Reino Road, Newbury Park, CA 91320 **Conejo Valley Unified School District** April 5, 2017

Opportunities for Improvement

Additional small shaded locations throughout the campus for dining, such as umbrella tables or seating under shade trees, will further enhance the collegiate feel of the campus.

Currently five portable buildings on campus (#'s 7, 18, 27, 28, 29) house assorted classroom and support spaces. These buildings are at the end of their useful life and are separated from the academic core of the campus. The construction of a new permanent classroom building that works with the central heart of the school to replace these portable buildings will provide equitable educational experience in a building that can enhance the overall

School personnel have reported issues with the central HVAC and electrical systems. Research into causes and the appropriate design solutions will improve performance and may subsequently reduce campus energy costs. Measures to reduce mineral build-up from hard water may lessen ongoing maintenance expenses.







Image C

5.0



Newbury Park High I Site Analysis

456 N Reino Road, Newbury Park, CA 91320 **Conejo Valley Unified School District** April 5, 2017


Opportunities for Improvement

(PER INSURANCE DOCUMENTS)

31. TOOL SHED

18. CLASSROOMS

updated and fresh look to the highly used space.





Newbury Park High | Site Analysis

456 N Reino Road, Newbury Park, CA 91320 Conejo Valley Unified School District April 5, 2017

Opportunities for Improvement

31. TOOL SHED



Address a current Title 9 complaint by providing a compliant softball field on campus or near-by.

Full renovation of the school's locker rooms, including plumbing fixtures, may provide high-quality support spaces to complement the school's high-quality athletic facilities.

A project to renovate the school's pool facilities is currently under way to address accessibility needs and health department inquiries.