

Existing Site Summary

Neighborhood:

Horizon Hills School is located in the City of Thousand Oaks on a 13.3 acre site bound by Greta Street (south), and Drayton Avenue (east). The major intersection is Greta Street and Avenida De Las Flores. The 23 freeway runs immediately east of the campus.

Instruction:

The school currently is part of the adult education program in the district and it serves an array of ages from preschool and parenting courses to adult education courses. The school has a pre kindergarten to age 5 for parents and kids, encompassing child/parent courses as well as single grade and mixed grade courses. In addition, there is a parenting program where parents are taught the fundamentals of raising children. There is also a whole series of adult education classes as well as community health classes that are offered in the southern building on campus, which is also where the multi purpose space is.

Summary of Facilities:

The main core buildings on the campus were built in 1968 which along with an exterior shaded courtyard create enjoyable exterior learning environment. An additional uncertified modular building was added in 2000, which currently has no plumbing hook ups. No major construction of buildings has occurred after the 2000.

The exterior landscaping and environment has received upgrades from the tenants of the school, but these have been superficial only. No major upgrades to systems or buildings have been made by the current tenants. The classroom finishes are very old, but are satisfying the needs of the current users.

There are a number of projects that have recently been completed or are in construction that include some access compliance, HVAC replacement, and LED lighting upgrades

Horizon Hills School | Survey

Building Systems:

The major building systems are original including, water, sewer and gas and are need of replacement. The HVAC system was renovated in 2006 and most of the roof was renovated in 2006 and 2008 with exception of classroom building 3 which has not been touched since 1992 and is in need of replacement.

Technology:

The site includes the Wi-Fi in every classroom, as well as projectors in all classrooms the campus has a computer lab for the older students needs. The campus makes an effort to be on the cutting edge of technology advancements in curriculum tools to enrich the lives of the students.

Energy:

The existing air handling units and cooling towers are beyond their life-cycle and will require replacement. Although they have been repaired they are old and in need of replacement. The entire campus has received an LED lighting upgrade which included occupancy sensors in every room. That has yielded a lower campus wide energy demand.

There is an opportunity for solar power generation as well to offset some of the energy demands of the school.

Site Attributes:

- Durable Masonry Construction Buildings
- Well Planned Shaded Courtyards with turf and play equipment
- Large recently updated Auditorium Space
- Mature enjoyable landscape and exterior environment
- Large parking are to accommodate parents and students


Site Deficiencies:

- Existing classroom finishes are old and outdated
- No clear entry point from street
- Flooding and drainage issues
- Electrical capacity is insufficient to current demand of campus
- Portable Building has no plumbing connection
- Need for accessibility upgrades

	Table of Contents
0.0	Cover Sheet
1.0	Table of Contents / Executive Summary
2.0	Cluster Context Map
	INSTRUCTIONAL INFORMATION
3.0	Project Location Plan & Data
4.0	Instructional & Campus Summary
5.1	Existing Campus Plan
5.2	Existing Campus Building Data
6.0	Existing Campus Building Use
7.0	Existing Campus Image Key Map
7.1	Existing Campus Images
7.2	Existing Campus Images
7.3	Existing Campus Images
8.0	Specialized Program
	FACILITY INFORMATION
9.0	Facility Certification Requirements
10.0	Site Challenges & Proposed Site Modernization Summary
10.1	Drop-off Points and Circulation
10.2	Facility Accessibility
11.0	Energy Use
12.0	Core Facilities Data
	TECHNOLOGY
13.0	Campus Technology
	PROJECT REQUESTS
14.0	Observations Summary



CVUSD Thousand Oaks Cluster



Legend

High School



CVUSD Thousand Oaks Cluster Sites

LOCATION CODE	SITE NAME	SCHOOL MANAGEMENT SERVICES SITE TYPE	GRADE LEVEL CONFIG
1 010	ACACIA ELEMENTARY	Elem. School	TK- 5
3 020	ASPEN ELEMENTARY	Elem. School	TK- 5
13 080	GLENWOOD ELEMENTARY	Elem. School	TK- 5
14 090	HORIZON HILLS	Pre K, Adult ED	MISC.
15 100	LADERA ELEMENTARY	Span Magnet	K- 5
18 120	MADRONA ELEMENTARY	Elem. School	TK- 5
23 170	PARK OAKS (BRIDGES)	Elem. School (Charter)	K- 5
24 180	REDWOOD MIDDLE SCHOOL	Middle School	6-8
27 200	THOUSAND OAKS HIGH SCHOOL	High School	9-12
29 220	UNIVERSITY	Elem. School	TK-5
31 240	WAVERLY	Adult ED / Special ED	MISC.
32 250	WEATHERSFIELD ELEMENTARY	Elem. School	TK-5
36 290	WILDWOOD ELEMENTARY	Elem. School	K-5
12 000	DISTRICT OFFICE	NA	NA
14	Totals Sites		


Community Resources

DESCRIPTION	LOCATION	CITY
Thousand Oaks Community Ctr.	2525 N Moorpark Road	Thousand Oaks
Thousand Oaks Community Park	2525 N Moorpark Road	Thousand Oaks
Conejo Valley Shopping Center	Moorpark Road	Thousand Oaks
Conejo Valley Art Museum	197 N Moorpark Road	Thousand Oaks
Conejo Community Center	1175 Hendrix Avenue	Thousand Oaks
Spring Meadows Park	3283 Spring Meadow Avenue	Thousand Oaks
Conejo Creek Equestrian Park	1350 E Avenida De Las Flores	Thousand Oaks
Glenwood Park	Windsor Drive	Thousand Oaks
Thousand Oaks Library	1401 E Janss Road	Thousand Oaks
Los Robles Hospital	215 W Janss Road	Thousand Oaks



Cluster Context Map

District Office







FACILITIES - CLASSROOM INVENTORY																				
		N	lumber of	Teachin	g Station	IS		F	Projection	s										
K-12 School	Grade/	Total # of			Modulars		[Tead	ching Sta	tions										
Facility	Type	Teaching	Permanent	Quality			Capacity	Rms	Ratio	Capacity										
		stations	A		Portables			Utilized		Needed										
	0 10			TOI THE IS	5/16 Scho	ooi reai			sed on 16					30						
	9 - 12	95	91		4		2850	77	30.00	2315				30						
														30						
	SDC	10	2		8			10	0					30						
PE = 1/6 of Population	PE	0					435	0	0											
	Free	-10	93			0	-300	-10	10											
Sub-Total 6-8		95	- 00			است	2985	77		2315										
						0				-										
			ENF	ROLLME	NT HIST	ORY														
Grade	2017	2016	2015	2014	2013	2012	2011	2010	2009	2008	2007	2006	2005	2004	2003	2002	2001	2000	1999	1998
9		498	519	615	535	581	547	609	666	592	648	624	662	686	680	720	631	666	680	627
10		507	606	546	582	547	594	661	582	649	638	652	673	662	690	649	663	657	631	577
11		603	538	574	522	601	640	536	626	590	622	649	644	644	604	638	623	602	557	594
12		511	554	519	571	626	540	566	560	609	623	610	631	552	603	589	575	513	564	545
																0		L		w
Total 9-12	0	2119	2217	2254	2210	2355	2321	2372	2434	2440	2531	2535	2610	2544	2577	2596	2492	2438		2343
Special Ed	0	79	72	85	74	73	94	99	88	63	59	48	49	64	59	48	47	49	34	39
TOTAL	0	2198	2289	2339	2284	2428	2415	2471	2522	2503	2590	2583	2659	2608	2636	2644	2539	2487	2466	2382
			DDIA	ICIDAL E	ROJECT	LIUNG												0.14	400.00	100.01
			FKII		KOJECI	IONS	Toos	her Calcul	lotion	Dudant								Opt 1 37	186.00	186.01
Grade	FORE	CAST	4/30/15	Carried from	8/19/15	TBD	By Grade			Budget Acctq								3/		0
Grade	Students	Teachers	4/30/13	previous	0/19/10	טטו	30.00		per class	Calc										
Special Ed	Ottacino	reactions	85	85	85		30.00	3-12	per olusio	Caic										
9	568	18.93	510	510	545		17.00		30											
10	548	18.27	610	610	639		20.33	77.17	30	0.4										
11	607	20.23	635	635	564		21.17	77.17	30	81										
12	526	17.53	560	560	578		18.67		30											
Total 9-12	2249		2315	2315	2326	0														
						<u> </u>	2400		0											
TOTAL	2249	74.97	2400	2400	2326		77			81										

Enrolment Data:

•For Secondary Schools

Classrooms 800 Square Feet and greater will be considered an "Available Classroom". On the color coded survey plan they can occur as BASIC CLASSROOM (Orange); SPECIALITY CLASSROOM (Light Blue); SCIENCE (Yellow).

If the rooms are being used for instruction and they are 799 Square Feet and under, they will be considered a "Small Room", with a different Color Code. Provide a description in the keynote as to its current use.

•For Elementary Schools

Classrooms 720 Square Feet and greater will be considered an "Available Classroom". On the color coded survey plan they can occur as BASIC CLASSROOM (Orange); SPECIALITY CLASSROOM (Light Blue); SCIENCE (Yellow).

If the rooms are being used for instruction and they are 719 Square Feet and under, they will be considered a "Small Room", with a Different Color Code. Provide a description in the keynote as to its current use.

For Span and other types of Schools

Identify what age group the space is used for the majority of the day – use rules above for Secondary Schools and Elementary Schools. Provide a description in the keynote as to its current use.


CVUSD ELEMENTARY SCHOOL											
	Location (Code: 14 (090	Campus Summary							
Site Information	Totals			Total Planne	d Site Capac	ity:	Ţ	Totals			
Current Useable Area:	19.7 Acres			Current Enroll	ment:		2	,300			
Current Playground Area:	7.5 Acres			Planning 2-Se	emester Capa	acity:	2	2,131			
				Enrollment to	use for Planr	ning	1	1,808			
				•							
Playground Area Required:	9.0 Acres										
	Current Clas	srooms		Potential Cla Classrooms	ssrooms + C	Current	Classrooms Identified by the School				
Classroom Status for School:	Permanen t	Portabl e	Totals	Permanent	Portabl e	Totals	Permanent	Portable	Tota Is		
Available Classrooms 800 Square Feet or greater:	25	20	45	25	20	45	22	15	37		
Available Small Rooms 799 Square Feet or smaller:	30	20	50	30	35	65	30	20	50		
Totals:	55	40	95	55	55	110	52	35	87		

CVUSD MAGNET SCHOOL	Location (Code: 500	0	Campus Summary			
Site Information	Totals			Total Planned Site Capacity:	Totals		
Current Useable Area:	Shared			Current Enrollment:	20		
Current Playground Area:	Shared			Estimated 2-Semester Capacity:	25		
				2013-14 Adjusted Projected Resident & Enrollment.	30		

CVUSD SPECIAL EDUCATION SCHOOL	Location Code: 3000			Campus Summary			
Site Information	Totals			Total Planned Site Capacity:		Totals	
Current Useable Area:	Shared			Current Enrollment:	10		
Current Playground Area:	Shared			Estimated 2-Semester Capacity:	9		
					& Magnet	10	

Analysis:

Add Campus Summaries as required for each existing school on a site.



Horizon Hills School | I Survey

33 Greta Street I Thousand Oaks, ca 91360

Conejo Valley Unified School District

November 1, 2016 Draft v1





PERMANENT

PORTABLE

SAND BOX PLAY AREA


X BUILDING NUMBER

PRIMARY POINT OF ENTRIES

BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- **5- RESTROOMS**

EXISTING SITE PLAN I HORIZON HILLS SCHOOL PERMANENT AND PORTABLE BUILDINGS





5.1



School		Building		Fire	Fire	Sprinkler	Fire	Alarm	Roof	Year		Yea Renov				Vacant	Flood	Zone	
District Sit Name	School District Building Name	Rating	Square Footage	Const.	Const.	Y/N	Y/N	Local/ Central	Type	Built	Roof	HVAC		Plumb		Is Vacant Y/N			Map Date
Horizon Hil	-	Elementary	7,674	2	Joisted Masonry	No	Yes	L	Composition	1968	2008	2006	2006	1968	Owned and occupied by the district	N	NS	Х	1/20/2010
Horizon Hil	ls	Elementary	8,595	2	Joisted Masonry	No	Yes	L	Composition		2008	2006	2006	1968	Owned and occupied by the district	N	NS	Х	1/20/2010
Horizon Hil	ls	Elementary	8,595	2	Joisted Masonry	No	Yes	L	Composition		1992	2006	2006	1968	Owned and occupied by the district	N	NS	X	1/20/2010
Horizon Hil		Portable	1,440	5	Modified Fire Resistive		Yes	L	Composition	2000	2000	2000	2000		Owned and occupied by the district	N	NS	X	1/20/2010
Horizon Hil		Elementary	1,672	2	Joisted Masonry	No	Yes	L	Composition	1968	2006	2006	2006	1968	Owned and occupied by the district	N	NS	X	1/20/2010



Existing Facilities:

4 buildings are over 40 years old

Analysis Summary:

The existing campus has been well maintained over the years but has received less funding in recent years for upgrades after the school was closed and converted into the new program. They did receive a campus wide LED lighting upgrade, but the current electrical capacity is maxed and causes them to have issues with breakers flipping. The campus needs electrical upgrades in both appliances and infrastructure which could help alleviate the electrical capacity issues.

The original buildings have aged well due to their masonry construction, the roof of building 3 is in need of replacement and the HVAC systems is very old and in need of replacement as well.





PRIMARY POINT OF ENTRIES

ADMINISTRATION

CHILD CARE

CLASSROOM

MULTI PURPOSE

OPERATIONAL SUPPORT

SUPPORT SPACES

VACANT CLASSROOM

SITE IMPROVEMENT KEY NOTES

- 1 PLUMBING AND WATER HOOK UP NEEDED
- DRAINAGE ISSUES, UNDERGROUND DRAINAGE NOT WORKING, LOCATION NEED TO BE REWORKED
- 3 NEEDS HANDRAIL TO CREATE ACCESSIBLE PATH OF TRAVEL TO UPPER BUILDINGS
- MAJOR ACCESS POINT TO SCHOOL NOT ACCESSIBLE. NEED TO CHANGE GATE

SITE IMPROVEMENT GENERAL NOTES

- OLDER CLASSROOMS WILL NEEDACCESSIBILITY UPGRADES ON HARDWARE THRESHOLDS AND SINKS
- EXTERIOR DRINKING FOUNTAINS WILL NEED TO BE MADE ACCESSIBLE
- ACCESSIBILITY UPGRADES NEEDED IN PARKING, GATE LOCATIONS, DOORS, AND SOME PATHWAYS
- SOME ACCESSIBILITY UPGADES NEEDED IN RESTROOMS TO BECOME FULLY COMPLIANT











PERMANENT

PORTABLE

SAND BOX PLAY AREA


BUILDING NUMBER

PRIMARY POINT OF ENTRIES

BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- **5- RESTROOMS**

IMAGE REFERENCE





Existing Campus Image Key Map

DRAFT

33 Greta Street I Thousand Oaks, ca 91360









Photo -1 **Building 5**

Primary entry location next to restrooms. Difficult to see from street.

Photo -2 **Building 1**

Multi Purpose building at the front of campus. Secondary entry point to campus through the multi purpose building.

Photo -3 **Building 3**

Shaded courtyard with artificial turf and preschool playground equipment. Nicely landscaped and well protected from the sun.

Photo -4 **Building 2**

Backside of building 2 is a playground area with artificial turf and play equipment. The equipment is well maintained.



Photo -5 **Building 2**

Sand box next to playground area has shade device and play equipment.

Horizon Hills School | Survey

33 Greta Street I Thousand Oaks, ca 91360

Conejo Valley Unified School District



Photo -6 **Building 3**

Gated entry to exterior landscaped area between building 3 and portable, newly updated with pavers and lush landscape.



Photo -7 **Building 3**

Exterior landscaped area between building 3 and portable, newly updated with pavers and lush landscape.



Photo -8 **Building 2**

Gutter system of building has been reworked but is currently spilling water on ground surface and then diverted to storm drains.





Photo -9
Building 3
Existing concrete pathways around the campus are old and cracking



Building 2
Covered concrete walkway between building 2
and 5 is very steep and does not comply with
accessibility standards

Photo -10

Photo -14



Building 1

Multi Purpose room with temporary stage. The temporary stage is borrowed from a different campus, school is in need of their own permanent stage

Photo -11

Photo -15



Building 1
Multi Purpose room has been recently updated with new fixtures and lighting. The PA system is in good working order.



Photo -13
Building 5
Typical thresholds have been updated throughout the campus



Building 2
New roof drainage to combat issues with ground drainage not working



Building 1
Interior Staff room in the multi purpose building that has older finishes and no accessibility upgrades



Building 1
Typical room in the multi purpose building used for unique classes like sewing



Photo -16









Photo -17 Building 2

Typical classroom with unique play equipment has updated floor finishes and good play equipment. Casework and sinks have not been upgraded

Photo -18 Building 2

Typical classroom with unique layout for prebirth parenting classes, has updated floor finishes and good play equipment. Casework and sinks have not been upgraded

Photo -19 Building 2

Typical classroom with unique play equipment has updated floor finishes and good play equipment. Casework and sinks have not been upgraded

Photo -20 Building 4

Portable classroom building is relatively new, but has no plumbing connection



Photo -21 Building 3

Typical sink in classrooms, not current with accessibility standards



Photo -22 Building 2

Staff room has newer floor finishes, Casework and sinks have not been upgraded



Photo -23

Building 2

Typical classroom with unique play equipment has updated floor finishes and good play equipment. Casework and sinks have not been upgraded, has additional sink/kitchen area



Photo -24 Building 2

Typical classroom with unique play equipment has updated floor finishes and good play equipment. Casework and sinks have not been upgraded



Classes Are Parent Participation

Core Classes Offered

Parent & Infant

0-6, 6-12, 12-18 months Parent & Toddler

18-30, 24-36 months

Classes meet once per week. Multiage (3-5 year olds) Classes meet 2, 3, or 5 days a week. 1:4 adult/child ratio.

On-site kiln for hands-on ceramics.

Additional Classes

Pre-Birth Parenting Baby Massage Afternoon Enrichment Activities Saturday Classes **Evening Parenting Classes** One-on-one Consultation

Parent Workshops & Discussions **Extended Day Picnic Pals**



Conejo Valley Adult Education A Division of the Conejo Valley Unified School District

Parenting Program & Preschool At Horizon Hills

A Parent Participation **Preschool & Parent Center**



A play-based preschool where the parents learn right along with their children

> Horizon Hills Campus 33 Greta Street, Thousand Oaks (805) 492-8837 www.conejoadultschool.org

Welcome to the Conejo Valley Adult School Parent Education Program **Early Childhood Center**

Celebrating 25 years at Horizon Hills

Come For Your Child, Stay For Yourself

The Parenting Program offers a unique experience in learning.

For Parents

We educate parents in raising self-reliant, wellbalanced children.

We utilize researchbased child development techniques to help parents build a solid parenting foundation.

become advocates for children.



For Families

We support families by providing a 650+ family network offering a wealth of opportunities for friendship and family connections.

Join us in our unique setting that provides a supportive community for you and your child.

For Children

We embrace the wonder and joy of learning inside every child.

We know the key to readiness comes from within; therefore we provide learning experiences through child-directed exploration, problem solving, and socialization using proven early childhood methods and research.



Horizon Hills School Parenting Program

This program is a true asset to the district, it offers a unique curriculum where parents come and assist with their children's pre education experience while at the same time being educated themselves on how to be a better parent. It offers bonding time with the parents and their children which is crucial to a child's development.

There are many different courses and none of them are prerequisites of each other which means that a child can enter the program at any point which is attractive to new students

The diversity of this program is what makes it a true magnet program offering parents a unique curriculum. While this program is similar to a charter program it is district run, after the children get older they will go to a district school, which means that this program is attracting children and parents to the district.





CERTIFIED

NOT CERTIFIED

SAND BOX PLAY AREA

X BUILDING NUMBER

PRIMARY POINT OF ENTRIES

BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- **5- RESTROOMS**





33 Greta Street I Thousand Oaks, ca 91360



PERMANENT



SAND BOX PLAY AREA



PRIMARY POINT OF ENTRIES

BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- 5- RESTROOMS



Site Challenges:

In its current condition, Horizon Hills School faces many challenges, the most pressing of which are directly related to aging buildings systems and drainage issues on site. The program is run quite differently than a traditional program in the district. This unique set up creates a very efficient operation that does not require some of the typical resources that other educational programs need. This would include the need for extensive playground area, multi purpose and assembly space as well as kitchen facilities. The campus does have these extra facilities but the spaces are used by the adult education portion of the campus.

ADA accessibility upgrades are needed to the main administration / auditorium / classroom buildings. In addition, accessibility upgrades to site / building drinking fountains and accessibility upgrades to access gates and building signage. Must be addressed during the modernization of the campus.

Site Modernization Opportunities:

Campus improvement opportunities as follows:

Modernization consists of projects targeted at improving the educational environment of classrooms and academic spaces, is developed around improving the overall condition and appearance of classrooms in permanent and portable facilities. The majority of this work is targeted at infrastructure related issues through campus, dealing with an old HVAC system and roofing upgrades. In addition, the roof drainage issues needs to be addressed.

Improvements in support spaces and arts spaces should advance the extracurricular components of the academic program. Specific improvements are targeted at providing plumbing infrastructure to the portable building on site as well as enhancing some of the finishes and casework in the classrooms. Improvements targeting boys and girls restrooms include minor cosmetic repairs such as patching damages and new paint throughout.

The modernization can be approached and structured on three levels: site infrastructure, site and building accessibility and building systems. Improvements to site infrastructure as stated earlier are intended to improve the efficiency of the buildings as well as handle the drainage issues that are present on the site. Improvements targeted at accessibility are to bring the campus to full compliance with current accessibility standards. Some of these improvements include new site and building signage, replacement of non-accessible door hardware, upgrade of student restrooms to include accessible stalls and fixtures and accessible entries to portable buildings. Improvements to building systems include the replacement of the HVAC system on all permanent buildings and on portable buildings without any pending HVAC upgrade.

In conjunction with the modernization is the need to enhance the aesthetics of the campus by creating an attractive new entry for the pre school area of the campus that will not only enhance the aesthetics of the campus as a whole but will also improve the wayfinding of the program making the entrance visible from the street.



Site Challenges & Proposed Site Modernization Summary

360

33 Greta Street I Thousand Oaks, ca 91360

Conejo Valley Unified School District

November 1, 2016 Draft v1






Image 1: Primary Entrance for Parent School Program



Image 2: Secondary Entrance through Adult School Building



•••• Access during school hours

BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- 5- RESTROOMS



Circulation Diagram



Horizon Hills School | Survey

33 Greta Street I Thousand Oaks, ca 91360

Conejo Valley Unified School District



BUILDING

- 1- MULTI PURPOSE BUILDING
- 2- CLASSROOMS
- **3- CLASSROOMS**
- 4- CLASSROOM (MODULAR)
- **5- RESTROOMS**



IMAGE REFERENCE



Photo -1 The current parking lot has accessible stalls, however they do not have detectable warnings and the pathway requires the pedestrians to use the parking lot to access the site.



Photo -2 Door thresholds throughout campus have been upgraded to accessibility compliant thresholds



Photo -3 The building sinks have not been upgraded to comply with accessibility standards




Photo -4 Currently there is no accessible path of travel to building 2, some minor modifications to one of the paths leading to the building will create an accessible pathway




Horizon Hills School | Survey

33 Greta Street I Thousand Oaks, ca 91360


Conejo Valley Unified School District

Energy Use Summary:

Currently the largest energy demand is the electrical use to power the HVAC system. The campus has received a LED lighting upgrade along with occupancy censors to improve the efficiency of the lighting system. However improvements can still be made when the HVAC system is replaced to improve the efficiency of the overall system. In addition to this there is solar power generation opportunities on the site due to the dry climate and ample sun and roof exposure.




Water:










Electrical:





Gas:

	Core Facilities		
Item	Category	Existing Square Footage	Standard Square Footage Based on Planning 2- Semester Capacity
1	Multi Purpose Building	7674 Square Feet *	00 Square Feet
2	Classroom Building	8595 Square Feet *	00 Square Feet
3	Classroom Building	8595 Square Feet *	00 Square Feet
4	Classroom Building	1400 Square Feet	00 Square Feet
5	Bathroom Building	1600 Square Feet	00 Square Feet
6	Playground	1.5 Acres	00 Acres
7	Parking	189 Stalls	00 Stalls

^{*(}Office Square Footage)

This calculation includes the Front Office/Main Office; Waiting Room/Space; Conference Room; Administrative Offices.



1. Multi Purpose Building

The mutli purpose building has been recently upgraded and the finishes are relatively new. The existing kitchen facilities are not in use and some of the building has been converted to additional administration offices.

2. Classroom Building

The classroom building has 2 classrooms that are empty and 1 classroom that is used as a staff lounge and meeting room. The facility has had recent HVAC retrofits and roofing replacements. There is currently no wheel chair accessible path to the building but this can be corrected with a minor change to one of the pathways. The casework is old and the sinks have not been upgraded to comply with accessibility standards.

3. Classroom Building

The facility has not had a recent HVAC retrofit or roofing replacement. The casework is old and the sinks have not been upgraded to comply with accessibility standards. The main administration/reception office is located in this building and there is an additional vacant classroom .

4. Classroom Building

This classroom is a modular building that was put on the site in 2000. The building currently does not have any water or plumbing lines.

5. Bathroom Building

The bathroom building has received some accessibility upgrades to the adult bathrooms but the children bathrooms have not been upgraded with exception to the thresholds all being compliant.

6. Playground

The playground area is much smaller than most schools, but a large playground area is not needed as much with pre school children who are receiving more direct supervision. The existing play equipment is relatively new.

7. Parking

The parking is sufficient to supply the needs of the campus. However the ADA stalls are not current with accessibility standards.



Core Facilities Data



Technology Summary:

Information to be proved by CVUSD Technology Department



Observations Summary:

Conejo Valley Horizon Hills School has a unique educational program that gives parents the opportunity to be a big part of their children's early education while at the same time being educated on proper parenting techniques. They offer programs in pre-birth planning, parent work shops and many other diverse programs in conjunction with a preschool environment where children from just a few months to 5 years can learn and grow together. This great magnet program to the district that has been seeing declining enrollment for the past several years. The program creates a relationship with the parents of these children and the school district that will then encourage them to remain in the school district for the remaining of the child's k-12 educational experience.

The school has not received any major updates or improvements in the past 10 years and the current state of the roof and HVAC system is in need of attention. One of the biggest challenges to the site that should be addressed is the roof drainage issue as this can lead to an increasing rate of building deterioration. In addition the electrical system is at full capacity and with the increasing technological demands of the future the need to improve the electrical systems is becoming increasingly more important.

One of the biggest concerns of the faculty at the school is the need for plumbing in the modular classroom building which they currently will carry large buckets or water to supply the classroom with water for the children for their arts and crafts.

The site is wonderfully landscaped and presents a realizing and enjoyable atmosphere where children can play and learn while being well protected from the sun. To enhance the aesthetics of the school, an improved entry to the upper portion of the campus, would help improve way finding from the street for new students as well as the overall feel of the campus itself.

